Megger.

Megger Head Office

Megger Limited Archcliffe Road Dover Kent CT17 9EN ENGLAND T: +44 (0)1 304 502101 F: +44 (0)1 304 207342

Manufacturing Sites

Megger Limited Archcliffe Road Dover Kent T: +44 (0)1 304 502101 F: +44 (0)1 304 207342

Megger USA - Dallas 4271 Bronze Way Dallas TX 75237-1019 USA T: +1 800 723 2861 (USA only) T: +1 214 333 3201 F: +1 214 331 7399 E: ussales@megger.com Megger GmbH Obere Zeil 2 61440 Oberursel, GERMANY T: 06171-92987-0 F: 06171-92987-19

Megger AB Rinkebyvägen 19, Box 724, SE-182 17 DANDERYD T: 08 510 195 00 E: seinfo@megger.com Megger USA - Valley Forge Valley Forge Corporate Center 2621 Van Buren Avenue Norristown Pennsylvania, 19403 USA T: 1-610 676 8500 F: 1-610-676-8610

Megger Baker Instruments 4812 McMurry Avenue, Suite 100 Fort Collins, CO 80525 USA T: +1 970-282-1200 F: +1 970-282-1010 E: baker.sales@megger.com E: baker.tech-support@megger.com

This instrument is manufactured in the United States.

The company reserves the right to change the specification or design without prior notice.

Megger is a registered trademark.

Microsoft and Windows are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.

Megger.



Baker AWA-IV Static Motor Analyzer

Quick Reference Guide

Part number: 71-050 EN V3

Baker AWA-IV Static Motor Analyzer

Quick Reference Guide

Part number: 71-050 EN

Revision: V3

Publication date: December 2018

Copyright Megger.

All rights reserved. No part of this handbook may be copied by photographic or other means unless Megger have before-hand declared their consent in writing. The content of this handbook is subject to change without notice.

Megger cannot be made liable for technical or printing errors or shortcomings of this handbook. Megger also disclaims all responsibility for damage resulting directly or indirectly from the delivery, supply, or use of this matter.

NOTICES

This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to Part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference with the equipment is operated in its installation.

This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the product manual, could cause harmful interference to radio communications. If this equipment does cause harmful interference, the user will be required to correct the interference.

Due to the phenomena being observed and the material properties being measured, this equipment radiates radio frequency energy while in the active test mode. Care should be taken to ensure this radio frequency energy causes no harm to individuals or other nearby equipment.

WARNING

Never exceed maximum operating capabilities of the Baker AWA-IV tester, power packs, or the Baker ZTX accessory. If using the equipment in any manner not specified by Megger, the protection provided by the equipment may be impaired.

Be sure to comply with all safety procedures prescribed by your organization, industry, and governing standards. Failure to heedsafety precautions can result in injury or death from severe electrical shock.

Additional information reference

The Baker AWA-IV Quick Reference Guide is intended to introduce users to the analyzer and its basic operating procedures.

For complete safety information and detailed information on the device, end-user license agreement, and CE conformity refer to the Baker AWA-IV User Manual.

1. INSTRUMENT DESCRIPTIONS	1
Baker AWA-IV 2 kV/4 kV model front panel	1
Baker AWA-IV 6 kV/12 kV model front panel	3
2. PREPARING FOR TESTING	4
Process overview	4
Creating or opening a database	4
Selecting a motor to test	5
Creating a new Motor ID	5
Creating a new Test ID	7
Selecting tests and setting up test parameters	10
3. BASIC TESTING PROCEDURES	16
Using the Explore, Motor ID, and Route tabs to find motors	16
Running tests automatically, semi-automatically, or manually	18
Test sequence	20
Reviewing test results/data	23
Printing reports	26

1. Instrument Descriptions

Baker AWA-IV 2 kV/4 kV Model Front Panel

All Baker AWA-IV series analyzers feature an eight-inch touch screen with a graphical user interface.

The interface features a logical layout of touch icons that improve ease of use.

Each tester's voltage capacity is identified by the markings found just below the touch screen.



Figure 1. Front panel controls for AWA-IV 2 kV and 4 kV models.

VGA port

The VGA port is used to connect the tester to a larger monitor (not included) foreasier viewing of test results.

USB ports

Industry standard USB ports are accessible from the front panel for connections to aprinting device, and data storage and retrieval devices.

Ethernet connector

The tester can be connected to a network via the ethernet connector.

Equipment stop button

This large, highly visible red button is easily pressed for immediate termination of high-voltage testing. It disconnects all high voltages from the test leads.

Low-voltage resistance test leads

Both sides of the connection clips must be in contact with the terminal of the motor being measured. Most recent AWA-IV 2/4kV testers have two low-voltage resistance test leads. Ensure that the leads are connected as shown in the example below.





Correct orientation

Incorrect orientation

Figure 2. Proper orientation of AWA-IV 2/4 kV 2-lead connectors.

AWA-IV6 analyzers use the high-voltage leads for low-voltage resistance testing (no additional set of leads).

AWA-IV 12kV analyzers have three red test leads for low-voltage resistance testing (no black lead).

High-voltage test leads

The Baker AWA-IV uses high-voltage test leads for surge, Baker ZTX, and DC testing. You must keep the leads clean and dry for best measurement performance.

The AWA-IV 6 KV model differs from the AWA-IV 12 kV with respect to test leads and procedures for use.

The AWA-IV 6 kV analyzer uses only one set of leads for both high- and low-voltage testing; it does not include a separate set of low-voltage test leads (shown as "low voltage resistance test leads" in the image).

Voltage output control knob

Turn the knob clockwise to increase the applied voltage or counterclockwise to decrease the voltage.

The rate of voltage increase or decrease is set via the touch screen interface.

Do not force the knob; turning the knob harder does not cause voltage to ramp any quicker and may damage the instrument.

BAKER AWA-IV 6 KV/12 KV MODEL FRONT PANEL



Figure 3. Front panel controls for Baker AWA-IV 6 kV and 12 kV models.

CAUTION

It is important to note that test lead clips have exposed metal areas. Do not touch the clips while tests are running. Always exercise care to ensure the clips are not placed in proximity to the frame or ground potential.

2. Preparing For Testing

PROCESS OVERVIEW

The basic process for testing a motor on the AWA-IV includes the following steps:

- 1. Open an existing database or create a new one.
- 2. Select an existing motor to test, or create a new motor (motor ID and test ID)
- 3. Select tests to run.
- 4. View and confirm test parameters, or modify test parameters.
- 5. Run tests automatically, semi-automatically, or manually.

Each step is described in more detail in this chapter.

CREATING OR OPENING A DATABASE

- 1. Start the Baker AWA-IV application by clicking on the icon on the tester screen or the MS Windows Start button.
- 2. Click on the appropriate radio button for creating a new database or opening an existing one.



Figure 4. Dialog box for creating or opening a database.

- 3. When creating a new database, a dialog box will open so you can name the new database. Enter the database name in the field then click **OK**.
- 4. When opening an existing database, highlight the database needed from the list and click **OK**.

SELECTING A MOTOR TO TEST

- Click on the **Data** tab to select existing motors, or to create and store information for new motors. Each motor will be listed in the **Explore** tab's **Motor Tree** on the left side of the screen. The **Motor Tree** provides a complete listing of all motors stored in a particular database.
- 2. To select the Motor ID for an existing motor, locate it within the **Explore** tab then click on the Motor ID to highlight it and to load its information in the **Data** tab.

🚾 Baker AWA-IV - [Example.mdb]								
File View Database Windo	w Tools Help							
🗅 🖻 🎒 🔯 📍 📃 👘	CoolFan332-2			3				
Explore Motor ID Route	Data Tests Trend	ling						
⊡ North Platte	Time	Test ID	Te	Res	Mo	PI	DC	Sur
🚍 Barrier Dam	3/19/2002 1:53:	480V w/o PI						FAIL
BD#3	3/19/2002 1:41:	480V w/o PI						FAIL
📋 Unit 2	3/19/2002 1:38:	480V w/o PI		PASS	PASS		FAIL	FAIL
CoolFan332-2	Location North Platte			•	1 6			
⊡ Unit 23	Building Upit 2				i V	Add		
	Motor ID: CoolEan222				1	Save		
CirFan30-23						Del		
Cmprcr22-454	Model: M1				− _/indi	na Confi		
South Branch	Manuf: Century Ele	etric			• Wi	ng conn Je	9	
Unit 17C	SN: 8-331258-0	1			C De	lta		
CirPump2323 -17C	Malta Datinar 220/400				г.			
	Vulis Hauriy, 230/460		∾. [1.0 uk [n	_		nou or la ar		
□ Unit 2	Volts Uper: 460 Volt	Ins			:	SF:[1.15		
CoolFan12-2	Amps Rating: 5.0/2.5	RPI	M: 1725	5	I	Hz: 60		
	Amps Oper: 2.5	Fram	ie: S145	5T	LR	(A): 9.5		
Unit 22L	NEMA Design: B	Amb °C:	40		LR	Code:	L	
Dalas B 05 22	NEMA nom eff: 0			Duty (Cycle: 🔽	ont	_	
Unit 22R	Manuf's Type: SC		Ma	nuf Dt Co	ode:		_	
Cnvvr23ALine2-22R	Description				J	-	-	
	Description.						0	
⊡ Unit 34R								
4160V 300RPM								

Figure 5. Using the Data tab to create a new motor.

CREATING A NEW MOTOR ID

- 1. If the motor you are testing does not yet have a Motor ID in the system, you will need to create a new Motor ID. To add a new Motor ID to the selected database, click on the **Add** button.
- 2. Click on the **Clear** button to remove all information currently entered in the fields.
- 3. Type the Motor ID, Location, Building, and name plate information in the appropriate fields.

NOTE

The labels for the **Location** and **Building** fields can be changed as desired by using the **Options** >**Changeable Labels** items in the **View** tab.

- 4. Best practices suggest adding all information pertinent to the motor to facilitate testing. This information can be useful during the testing and troubleshooting processes.
- 5. Click on the **Save** button to add the motor information to the database.
- 6. The Select Test ID dialog box will appear so you can assign the most appropriate Test ID to the motor. Test IDs contain the testing parameters (for example, tests performed, voltages, and pass/ fail criteria) along with a basic motor description.

For example, a Test ID named 480Vw/Rotor>100HP StepV includes tests for a 480-volt motor that has the rotor installed during testing, is less than 100 horsepower and will feature step voltage testing.

7. Click **OK** after selecting the best available Test ID for the motor you will be testing.

Explore Motor ID Route	Data Tests Trending
Explore Motor ID Route P-North Platte B-Barrier Dam ColFan332-2 B-Unit 23 D-Unit 23 D-Unit 45A B-South Branch B-Willow Ridge	Data Tests Trending Time Test ID Te Res Mo PI DC Sur 6/16/2016 3:53: 6900V w/ Location North Platte Reset Building Unit 2 World ID: Bldg Vent Fan Clear Model: BVF 4160A Winding Config © Wye Delta Volts Rating: 4160 HP/KW: 4 Enct: Volts Rating: 15 RPM: 6400 Select Test ID Amps Oper: 12.5 Frame: S145T Select a Test ID to be used when Testing this motor. NEMA Design: B Amb °C: 40 Det (= 1) Det (= 1) <t< td=""></t<>
	NEMA nom eff: Due Default Default De
	Description:

Figure 6. New motor added to Motor Tree. Information entry and Test ID selection.

- 8. The new motor will appear in the motor tree on the left side of screen.
- 9. You can then view the tests selected for the motor along with the test parameters then make adjustments if needed to better suit your testing objectives.

CREATING A NEW TEST ID

If a Test ID does not exist for the motor you want to test, you can create a new one for current and future use.

- 1. Click on the **Tests** tab.
- 2. Click on the Edit Test ID checkbox to enter edit mode.
- Test IDs can be password protected if desired. If a password has not been set up and you want to use one, enter a new one in the **Password** field. To change a password, click on **Change Password**, type in the current password (if applicable), enter the new password and confirm then click on **Set Password**.
- 4. Click **OK** to close the password dialog box.



Figure 7. Setting a password within the Tests tab.

- 5. Click the **Add** button. The Create New Test ID dialog box appears.
- If an existing Test ID is close to what you will need, ensure that it is selected in the Test ID field then click on the Copy Current Test ID radio button. Otherwise, click on the Add Blank Test ID radio button to start from scratch.
- 7. Give the new Test ID a descriptive name and choose a target motor voltage class from the drop down list then click on **OK**



Figure 8. Create New Test ID dialog box.

 You can further modify the Test ID by selecting the desired tests to be performed via the On/ Off buttons

Data Test	ts Trending	
Test ID: 41	60V w/Rotor Ram	p 🚽 🗹 Edit Test ID 🗖 Enable Calibration
For: 416	0 Volt 🖵 Motor:	Save
,	_	Run Auto Test Add
- Temperatu	ure/Resistance Te	Delete
	Iemperature	Manual
ON	R <u>e</u> sistance	3 Lead/Low V
- DC Tests		
ON	<u>M</u> egOhm	5000 Volts
ON	DA Only E I	5000 Volts
ON	Ramp-Voltage	9300 Volts Configure/View DC Test parameters.
- Surge Tes	t <u>S</u> urge	9300 Volts
\bigcirc		

Figure 9. Selecting tests to perform, and controls for configuring or viewing test parameters.

9. You can also provide specific values and parameters for each test as needed by clicking on the Configure/View buttons. In the following example, DA Only is selected from the DA/PI tests drop down list and Ramp Voltage is selected from the HiPot/Step Voltage test list.



Figure 10. Selecting test parameters from the DC Tests Setup screen.

10.Click **Save** to save the changes made to the new Test ID or click **OK** in response to a confirmation dialog appearing after making parameter changes. The new Test ID will be added to the list.

SELECTING TESTS AND SETTING UP TEST PARAMETERS

As noted in the process for creating a new Test ID, you can select which tests you want to run for a selected motor by clicking on the **ON/OFF** buttons for each test type. You can also view and configure parameters for each test type by clicking on the buttons in the right column for each test type.

Data Tests	Trending			
Test ID: 416	:0V w/Rotor Ram	p 🔽	Edit Test II	📔 🗔 Enable Calibration
For: 4160) Volt 👻 Motors	3	Save	
,		<u>R</u> un Auto Test	Add	
⊢ T <u>emp</u> eratur	re/Resistance Te	ests	Delete	
	<u>T</u> emperature	Manual		
ON	R <u>e</u> sistance	3 Lead/Low V		
- DC Tests -				
ON	<u>M</u> egOhm	5000 Volts		
ON	DA Only PI	5000 Volts		
ON	Ramp-Voltage	9300 Volts	nfigure/View	v DC Test parameters.
-Surge Test				
	<u>S</u> urge	9300 Volts		
\bigcirc				J

Figure 11. Selecting tests to perform, and controls for configuring or viewing test parameters.

NOTE

The following sections provide brief introductions to each test setup screen. For details on the screens and the parameters set within, refer to the AWA-IV user manual.

SETTING UP TEMPERATURE AND RESISTANCE TESTS

- To enter the temperature value and set up resistance tests, click on either the Manual or 3 Lead High V button.
- 2. The Temperature/Resistance Test screen appears so you can provide the information needed for your test.
- 3. Using this screen, you can enable or disable temperature entry or resistance testing, select specific parameters to include in your testing, or adjust testing parameters to fit your needs.

Temperature/Resistance Test AWA	4				
				Cancel	Close
◯Temperature Enable					
⊙ Manual Temperature E	ntry		0 <u>*</u>	Accept	°C
🗖 Relative Humidity (@	-100%)		0	Accept	
○ Resistance Enable	○ 2 L	eads	(1 phas	e) 💿 Auto	omatic
Winding Config:Wye	💿 3 L	eads	(3 phas	e) 📃 Res	Leads
☑ Delta R (%)	3 -			o nani	Jal Entry
Correct to	25 °C 🧕	Coppe Alum.	er 23	4.5 IEEE Const	118 ant
Target Corrected F	Resistanc — Test Re	e sult		8.0+/-	0 - %
	- Test no	Surt			
Test All Leads	Measure Balance		Tem Corre	ip Cal cted C	Lcuated oil R
Lead 1+2 3(Ohms)	0.	0Ω		0.0Ω	Ω
Lead 2+3 1(Ohms)	0.	ØΩ		0.0Ω	Ω
Lead 3+1 2(Ohms)	0.	ØΩ		0.0Ω	Ω
Delta R (Max-Min)/Avg		%			
1					

Figure 12. Temperature/Resistance Test setup screen.

- 4. The Test Results section shown at the bottom of the screen provides a view of the results collected when the test runs automatically or semiautomatically. You can also use this section directly during manual testing.
- 5. When you have completed your setup, close the screen.

SETTING UP DC TESTS

- 1. Enter into the DC Tests setup screen by clicking on any of the voltage buttons next to the DC tests listed.
- 2. Using this screen, you can enable or disable test types, select DC test types to include in your testing, select specific parameters to include in your testing, or adjust testing parameters to fit your needs.
- 3. You can use the default values provided, or you can modify parameters based on IEEE, EPRI, EASA, IEC, or company standards.



4. Depending on the test types selected, other controls may appear within the screen.

Figure 13. DC Tests setup screen.

- 5. If you want to use temperature correction for your DC tests, check the Temp Correction Enable box (even if you have checked this option in the resistance test setup screen.
- 6. The "Run Tests" buttons near the bottom left of the screen are used to control testing during manual testing. The Voltage and Current displays to the right show you value being measured during testing.
- 7. When you have completed your setup, close the screen.

SETTING UP A STEP-VOLTAGE TEST

1. From the DC TESTS screen, click on the drop-down list for **HiPot/Step Voltage** then click on **Step Voltage** as shown in the image below. This will open the Config Wizard.



Figure 14. Setting up Step-Voltage test parameters.

2. Set each value to a desired level and click **Next**.



Figure 15. Step-Voltage Configuration Wizard; setting voltage parameters.

- 3. Add or delete steps within this screen as needed, then click **Finish** to save the setup.
- 4. When you have completed your setup, close the screen.

End-Step I S	Step-V	oltage Configurat	ion Grid
-Current(µA)	Step Vol	ts (V) Time(s	Min Meg
Voltage	1 500) 60	1
	2 100	00 60	1
4500	3 150	0 60	1
1000	4 200	JO 60	1
2500- 2000- 1500- 1000- 500-			
0 0. 7 7. 2	Ad	d Sten	Del Step

Figure 16. Step-Voltage Configuration Wizard; adding steps.

SETTING UP A SURGE TEST

- 1. Click on the voltage button in the **Surge Test** section to enter the setup screen.
- 2. Using this screen, you can select options to use during testing, select parameters to include in testing, and specify test parameter values.
- 3. Enter parameters based on IEEE, EPRI, EASA, IEC, or company standards.
- 4. Set Pass/Fail tolerances as needed for the motor under test.
- 5. You can also check the **ZS Override** button if you want the tester to automatically start at the **Surge Voltage** level, removing the need to ramp up and allowing the tester to reach the target voltage faster. This feature is available only for semi- automatic or manual testing. Additionally, the feature cannot be saved as part of a Test ID.
- 6. The large graph area plots the surge waveform during testing.
- 7. The Run Surge controls are used during manual testing.

WARNING

When using ZS (Zero Start) Override, test voltage will not start at zero. Because the tester will immediately apply higher test voltages to the motor, take all precautions to avoid injury or death from severe electrical shock.

Surge Test					
Surge Voltage	500 -	Set Pass/Fa	il Tolerances		Close
VRamp Rate	25 .	☑ L-L EAR (%)	10 <mark>÷</mark> L1	L2 L3	
Surge Pulses	10 -	☑ P-P EAR (%)	10 ÷		
Volts/Div	Auto	🔽 Zero Crossing(%)	10 ÷		-Run Surge-
μ Seconds/Div	Auto	📕 Test-Ref EAR(%)	10 ÷		Lead 1
🔲 Enable PP	🗌 Pause Be	tween Leads 📃 ZS Ou	verride	Е	Lead 2
			1 1 1 1		Lead 3
1500				- 1	All Leads
0 1000 E				- 3	
L 750					
T 500				1 1	Peak Voltage
G 250				-	L2 0
E 0					L3 0
-250				1 1	L-L EAR (%)
-500					2-3 0
-750				- 1	3-1 0
-1250				E	
-1500					
	<u> </u>	I I I I I I I	1 1 1		
0 2	.5 5.0	7.5 10.0 12.5 μSECONDS	15.0 17.5		

Figure 17. Setting up Surge test parameters.

8. When you are satisfied with your specifications, close the Surge Test setup screen.

When you have completed the processes for selecting an existing motor ID, creating a new motor ID (and Test ID), selecting tests to run, and confirming or modifying test parameters, you will be ready to run the tests on your motor. Details for running tests automatically, semi-automatically, or manually are provided in the next section along with other operating procedure information.

Surge testing through capacitors

The surge test is load dependent. Anything that adds capacitance to the motor or system under test will create more load on the tester.

When surge testing a motor, all capacitors should be removed or the ground should be lifted. Otherwise, the capacitors will absorb the surge pulse, preventing it from entering the coils.

Rotor effect on testing

When possible, remove or secure the rotor before testing. Rotors can affect testing results, particularly if they move (even slightly) during testing.

Some issues can be erroneous high resistance imbalance in coil testing due to increased inductance, inability to polarize for DA/PI testing, or frequency shift in one or more waveform values during surge testing.

An erratic PP EAR will often result, and the shift could even trip the EAR limits.

3. Basic Testing Procedures

USING THE EXPLORE, MOTOR ID, AND ROUTE TABS TO FIND MOTORS

The left side of the screen is used to navigate through the motors within the opened database Three methods can be used:

The Explore tab

The **Explore** tab includes a tree structure to help you select a particular Motor ID. The two upper levels of the tree correspond to the location and building in which the physical motor is housed **Location** and **Building** are the default tree labels, but they can be changed. The lowest level is the Motor ID.

The Motor ID tab

The **Motor ID** list box provides an alphabetical listing of all motors found in the database. In the edit box located above the list, the currently selected Motor ID is displayed. Locate a Motor ID using one of two ways within this tab:

- Begin typing the desired Motor ID in the edit box. The list will automatically scroll to the nearest Motor ID that begins with those characters.
- Otherwise, scroll down the list until the Motor ID is located. Double click on the Motor ID or highlight the Motor ID and click the **Display** button to select.

The Route Tab

The **Route** tab allows construction of individual lists of Motor IDs for routing purposes. As seen in the example, the "Spring Outage" list is selected. This list has four associated motors.

You do not need to search the entire database to find the motors to be tested during the "spring outage" event. This tab also allows you to edit and print the routes. To select a motor, simply click on the motor name in the route list. Click on the **Edit Route** button to start the editor.

The Route Editor dialog box appears to help you add, rename, and delete routes. It also provides tools to add, remove, and change the order of the Motor IDs within a list.

Route Editor			×
Routes:			
Spring Outage 📃	Add	Rename	Delete
Route Motors:	A	vailable Motors:	
CirFan34-23 CoolFan332-2		4160V_300RPM BD#3	
CoolFan12-2 Cmprsr32-45A	<< Add	CirFan36-23 CirPump2323 -17C CirPump2343-17C	
	Remove >>	CirPump3233-22L Cnvyr23ALine2-22R Cnvyr23BLine2-22R	
	Remove All	Delco_B-95-22L	
	Save List		
Move Up Move Down			Close

Figure 18. Use the Route Editor to manage route information.

Running tests automatically, semi-automatically, or manually

After you have selected a motor for testing, completed selecting the tests you want to run, and made adjustments to the test parameters (if needed) you can simply click on the red Run Auto Test button found in the Tests tab.

The software will then execute each test in turn, providing you with visual cues along the way for setting up test leads, entering temperature values (if selected), and displaying test results within the related test screens.



Figure 19. Controls used to run automatic and semi-automatic testing.

You can run tests semi-automatically by clicking on the individual test type buttons found in the **Tests** tab. The software will perform the same functions as during automatic testing, but only for the selected test.

As noted in the setup screen descriptions, each screen has controls for manually executing tests. Resistance and surge tests even allow you to test individual leads. Tests can also be run manually using the analyzer's front panel controls.

	Test Results							
Test i	All Leads	Measured L-L	Ten Correc	p ted	Calcuated Coil R			
Lead 1	-2(0hns)	0.0	Ω	0.0Ω		Ω		
Lead 2	-3(0hns)	0.0	Ω	0.0Ω		Ω		
Lead 3	-1(0hns)	0.0	Ω	0.0Ω		Ω		
Delta R (Hax-Min)/A	lvg	2					
DC TESTS AWA	4							
	A	0	A					
Tort Tuno	O UN	UN	UN	_				
Test light	Megohm	PI 💌	HiPot	-				
Test Volt	5000	5000	9388					
Man Heg	100	189	199	2750	Run	Surge		
VRamp Rate	25	25	10	2500	Le	ad 1		
Time(s)	68	688	60 -	2250	Le	ad 2		
Trip I(µA)	1000	1888	1000	2886	Le	ad 3		
Dischg Time(m)	0	0	0	1756	A11	Leads		
Hin PI		2 -		1250				
Feeble DD			-	1000				
chapte PP				750				
R	un Test	Run Test	Run Test	586				
	Run Selected Tests							
– L		Serecced rea	.es					

Figure 20. Controls within setup screens to run tests manually.

An automatic test will analyze the motor in the following sequence:

- 1. Resistance
- 2. Megohm
- 3. PI/DA
- 4. DC HiPot/DC Step Voltage
- 5. Surge

NOTE

The actual tests performed will depend on the tests you select for your motor.

At the end of the sequence, the test data will automatically be saved to the database.

- 1. To start an automatic test, ensure that the motor is selected.
- 2. Click on the **Tests** tab to get to the main testing screen.
- 3. To start the test, click on the red **Run Auto Test** button and follow the directions.
- 4. The Safe To Turn On dialog box appears when a high-voltage test is selected. Typically, it instructs you to verify that the correct set of leads have been properly connected; however, the content of the message can vary depending on your tester configuration.



Figure 21. Safe to Turn On dialog box; message content can vary.

5. Follow the instructions in the dialog to continue the testing process. When all tests have been run, the test data will automatically be saved to the database and the main test screen will reappear.

NOTE

Not all Baker AWA-IV testers have low-voltage test leads. If this option is not available, this screen will be slightly different; however, the test operation is the same.

TEST SEQUENCE

The following sequence of tests will run automatically. If a test fails, the software will stop the testing process, leads will be discharged and grounded, and you will be presented with choices for continuing testing if applicable.

Under most circumstances, you should troubleshoot, diagnose, and repair the motor before going on to the next test in the sequence.

Temperature entry

The Temperature/Resistance dialog will be displayed ready for the temperature reading to be entered from a third-party temperature device.

- 1. Enter the temperature of the motor and click the **Accept** button to acknowledge the temperature being entered.
- 2. Click **Next** to proceed. The tester will automatically proceed with the remainder of the tests.

Resistance

This test looks for resistance imbalance between phases. If a large imbalance is found, inspect the motor for causes of the discrepancy. By comparing the values to a reference standard, you can evaluate the following quality and degradation issues:

Field testing — Inspect connections in junction box and look for high resistance connections, and improper or loose connections.

Quality/post failure — Look for number of turn per phase variation, diameter copper variation, turn-to-turn shorts, or turn opens.

Megohm

A Megohm test uses a test voltage close to the motor's operating voltage and appropriate standards and/or company guidelines. This voltage will be held for 60 seconds during which the analyzer watches for overcurrent conditions and microarcs or insulation resistance values below the minimum megohm setting.

Look for an unusually low Megohm value when compared to previous measurements or industry accepted limits. If a low Megohm value is measured, inspect the motor for ground wall insulation damage.

PI/DA

The Polarization Index (PI) test measures the insulation's ability to polarize. When an insulator polarizes, the electric dipoles distributed throughout the insulator align with the applied electric field. As the molecules polarize, a polarization (absorption) current develops and adds to the insulation's leakage current.

The additional polarization current decreases over time and drops to zero when the insulation is completely polarized.

The PI test is typically performed at 500, 1000, 2500, or 5000 volts depending on the motor's operating voltage. The duration of the PI test is 10 minutes (600 seconds). The PI value is calculated by dividing the insulation resistance at 1 minute by the resistance at 10 minutes. In general, damaged insulators will show a low polarization index.

Many insulating materials do not easily polarize. If the 1-minute insulation resistance is greater than 5000 Megohms, the PI measurement may not be meaningful. The PI test is performed on motor 100 Hp or greater. Motors less than 100 Hp should use the Dielectric Absorption (DA) test. On the AWA, set the PI minimum alarm at 2.0 for class B, F, and H insulation, and 1.5 for class A insulation.

The PI test should not be used as the basis for any motor acceptance criteria. It should be used as a trending and diagnosis tool along with other test results, including the PI curve generated.

If the Test ID was set up for a DA test, the test duration will be three minutes (180 seconds).

DC HiPot/Step Voltage

The HiPot test is performed at a test voltage higher than the Megohm test; that is, at voltages typically encountered at start-up. Actual test voltages are based on the motor's operating voltage and appropriate standards and/or company guidelines.

Look for unusually high leakage currents or a leakage current that does not stay constant. High leakage currents indicate weak ground wall insulation.

During a Step Voltage test, voltage is applied to all three phases of the winding and raised slowly to programmed levels then held for a predetermined period. This process is executed in equal increments (steps) until the target maximum voltage level is reached.

Because the test is most stable at the end of each step, data is logged at this point. If the leakage current doubles from a given step to the next, an insulation weakness is indicated and testing should be stopped. If leakage current increases consistently less than double, the motor insulation is likely good.

Surge

Effectively an electrical resonance test, the Surge test creates a nonlinear voltage drop across the windings, stressing the turn-to-turn insulation. If weak insulation exists, the differential voltage will short out a bit of the winding, causing the overall inductance to go down.

Surge testing measures pulse-to-pulse EAR (Error Area Ratio) by default, and can also measure line to-line EAR. (Refer to the AWA-IV User Manual for details on Surge testing and EAR measurement

During testing, the voltage will be slowly increased on lead 1 to the voltage specified in the Test ID.

If no pulse-to-pulse EAR failures are detected, leads 2 and 3 will be tested.

A shift to the left in the waveform patterns is a common indicator of weak insulation.

Failure modes	Winding Resistance	Meg test	PI test	Step Voltage	Surge
Weak insulation turn-turn					Х
Weak insulation phase-phase					Х
Weak insulation coil-coil					Х
Turn-turn shorts	Х				Χ
Phase-phase shorts	Х				Х
Coil-coil shorts	X				X
Open coils	Х				Χ
Reversed coils					Х
Unbalanced phases	X				Х
Weak ground wall insulation		X	X	Х	X
Dirty windings		X	Х	X	
Moisture		Х	X	X	
Faulty feeder cables		Х	Х	Х	Х
Motor lead line connections	Х				

Figure 22. Fault analysis chart.

Reviewing test results/data

After the test results have been saved to the database, they can be reviewed using the **Data** tab on the right pane of the analyzer software main window.

The **Results Summary tab** (accessed from the bottom of the pane) presents a Date/Time section at the top of the screen and a spreadsheet style view occupying the main display area.

Data Tests	Trending						
Time	Test Id	Temp	Res	Мо	PI	Hipot	Srg
03/26/12 11:54:	Delco_460/	PASS	PASS	PASS	PASS	PASS	PASS
03/25/12 11:12:	Delco_460/	PASS	PASS	PASS	PASS	FAIL	
03/22/12 12:00:	Delco_460/						

Figure 2	3. Data	tab s	showing	example	results:	Date/Time	window.
inguic 2	J. Dutu	can .	monnig	champic	icsuits,	Dute, mile	

The Date/Time section shows a summary of the time and date of tests, and whether the tests passed or failed. Clicking on a specific test date/time loads the test records for that event into the main display area.

The spreadsheet style of the results view shows the actual test data acquired. The test date and time are shown in the first two rows. A header row marks the start of a results section for each test category followed by the specific test measurement results.

Color coding helps you see whether a test category includes all passing tests (green) or failing results for specific measurements (red).

Time	Test	ID Tem	p Resist	Mohm	PI	DC	Surge	
4/2/2012 9:3	5:4 Delco_46	0/wPI Test	ed PASS	PASS	PASS	PASS	PASS	
3/26/2012 11	:5 Delco_46	0/wPI Test	ed PASS	PASS	PASS	PASS	PASS	
3/25/2012 11	:1 Delco_46	0/wPI Test	ed PASS	PASS	PASS	FAIL		
Test Date	4/2/2002	3/26/2002	3/25/2002	3/22/2002				e e e e e e e e e e e e e e e e e e e
Test Time	9:36:40 AM	11:54:04 AM	11:12:00 AM	12:00:00 PM				
Temp Status	Tested	Tested	Tested	No Test				
Temp(°C)	23.0	24.0	25.0					
Resist Status	PASS	PASS	PASS	No Test				
Bal L1 (Ohms)	3.137 Corr: 3.1	3.156 Corr: 3.1	3.142 Corr: 3.1					
Bal L2 (Ohms)	3.172 Corr: 3.1	3.188 Corr: 3.2	3.175 Corr: 3.1					
Bal L3 (Ohms)	3.088 Corr: 3.1	3.104 Corr: 3.1	3.096 Corr: 3.0					
L1-L2 (Ohms)								
L2-L3 (Ohms)								
L3-L1 (Ohms)								
Max Delta R %	2.600	2.600	2.500					
Coil 1 (Ohms)	2.096 Corr: 2.1	2.110 Corr: 2.1	2.099 Corr: 2.0					
Coil 2 (Ohms)	2.142 Corr: 2.1	2.152 Corr: 2.1	2.142 Corr: 2.1					
Coil 3 (Ohms)	2.030 Corr: 2.0	2.040 Corr: 2.0	2.038 Corr: 2.0					-
Megohm Stat	PASS	PASS	PASS	No Test				
Volts (V)	510	510	510					
I(μA)	0.4	0.4	0.4					
Resist	1275	1275	1275					
At 40°C	392	420	450					
PI Status	DA Only	DA Only	DA Only	No Test				
Volts (V)	510	510	510					
DA Ratio	1.0	1.0	1.0					
Nameplate	Application	Results Summany	Burge PI	Sten/Ramn-V	oltage			

Figure 24. Example test results summary view.

The Surge, PI, and Step/Ramp Voltage test results can be viewed using the dedicated tabs found at the bottom of the pane.

For example, review the PI test by clicking on the **PI** tab. The PI view will display the PI/DA graph along with a table of the current and megohm readings gathered at specific times. The PI voltage, DA ratio, and PI ratio are displayed on the right side.

Data Tests Trendi	ng							
Time	Test ID	Temp	Resist	Mohm	PI	DC	Surge	
9/9/2012 10:23:	6600V w/PI	Tested	PASS	PASS	PASS		PASS	
——I(µA)	PI Ratio			PASS				
Megohms				5000 Volts				
60			-140	1.3 DA				
50 ×			-120	1.3 PI				
			-100					
			-80 E	Megohm Plot	7			
8 30			60 2	E Car Data				
- 20-			-40	Sec Data				
10-			-20	Current Plot	-			
0			L0	🔲 Min Data				
0 1 2 3	4 5 6 /	8 9 10		🔽 Sec Data				
	Time (Minutes)							
Time (Min	l líuAl	Meaohm	s					
0:15	144.30	34						
0:45	118.70	42						
1:00	113.30	44						
1:30	104.50	47						
2:00	97.00	51						
3:00	94.80	52						
4:00	91.50	54						
5:00	89.00	56						
7:00	86.50	57						
8:00	85.50	58						
9:00	84.70	59						
10:00	84.00	59						
Namenlate Applic	tion Results Sur	mmany c		Stan/Ramp-Vo	Itage			
Applica	Allon Alesuits Sur	Sumary Su	Me I MI	Step/Kamp-Vo	itage			
							N	UM

Figure 25. Example PI test results.

The Surge test data can be reviewed by pressing the **Surge tab**

Data Tests Trending
Time Test ID Te Res Mo PI DC Sur
10/4/2010 11:4 GP 2300's T PASS PASS PASS PASS PASS 10/4/2010 11:2 GP 2300's
Ny Ny Long Tribun of Long J
Surge Waveforms Lead
Nameplate Application Results Summary Surge IPI Step/Ramp-Voltage

Figure 26. Example Surge test results.

Printing reports

Complete report generation features are available to document test results for managers, customers, owners, repair personnel, and more. Reports contain test, nameplate, and application data and can be sent to a printer or output as an RTF file.

You have three options for starting the **Report Generator:**

- Click on the File menu then the Print menu item.
- Hold down the control key and press "P" on your keyboard.
- Click on the printer icon in the upper left of the main screen.

The **Select Filters** section of the Report Generator dialog contains a selection of print filters. Check the **Current Motor/Test Results box**, or use any combination of the filters such as a date range and all motors that fail any test during a given test range.

The **Select Reports** section provides a list of available reports and report options.



Figure 27. Report Generator dialog.

The simplest report to generate is the current test results, which appear to the right of the **Current Motor/Test Results** check box. Check the box then select which report(s) you want to generate.

NOTE

For more detailed information on printing reports along with additional information on testing, results analysis, recommended test voltages, applicable standards, data transfer, and more refer to the Baker AWA IV User Manual.