

1010 IAQ Meter



Delivering test and measurement advantages for HVAC/R professionals worldwide

Test the TPI advantage

APPLICATIONS

- Check ambient CO and CO2 levels in work and living spaces
- Monitor results of air control systems
- Ambient air temperature and Humidity
- Test dew point and wet bulb humidity



FEATURES & BENEFITS

- Calculate percent outside air to maintain acceptable CO2 levels in buildings and work spaces
- Measure and display Carbon Dioxide (CO2) and Carbon Monoxide
- Measure ambient air temperature
- Measure relative humidity, dew point and wet bulb
- Log up to 4,000 readings in 1 second to 23 hour 59 minutes intervals
- Download to a computer using the A368 USB cable

TRANSCAT

▶ Visit us at Transcat.com!

35 Vantage Point Drive Rochester, NY 14624
Call 1.800.800.5001

MEASUREMENTS

CO2
Temperature
Relative Humidity
Dew Point
Wet Bulb
CO

RANGES

0 to 5000ppm
-4 to 140°F (-20 to 60°C)
5 to 95%
-47 to 135°F (-44 to 57°C)
3 to 135°F (-16 to 57°C)
0 to 500ppm