



Pneumatic glove tester

Pneumatic Glove Tester

This rugged, molded air pump conveniently tests all types of rubber gloves with a cuff diameter of 5 in. (127 mm) or less. A built-in check valve retains pressure within the glove as long as desired. Tester is provided with two fabric-covered elastic sealing rings.

Length: 5.5 in. (140 mm)

Diameter: 5 in. (127 mm)

Weight: 1.5 lb (0.7 kg)

OPTIONAL ACCESSORIES

Piezo Verifier

This essential safety tool is used to confirm the correct operation of voltage detectors and phasing testers that do not have a self-testing capability. When the verifier handle is depressed at the rate of 3 strokes per second, a piezo crystal generates approximately 1800 volts. This voltage, when applied to the tip of the detector, tests for integrity of the current path and proper operation of the indicators.

A three-step procedure of testing the detector with the piezo verifier, using the detector to test for the absence of high voltage and then testing the detector again should be strictly observed in accordance with accepted operating procedures. Verifier can be used with single- and two-pole models.

Supplied with case and lead

Length: 7 in. (178 mm)

Weight: 0.75 lb (0.34 kg)



Piezo verifier

ORDERING INFORMATION

Item	Cat. No.	Item	Cat. No.
For DETEX Voltage Detector and Phasing Tester ordering information, refer to Specifications table.		Optional Accessories	
Included Accessories		Protective fiber case	
DETEX Voltage Detectors		for Cat. No. 514360-1/514440-1	513572
Carrying case, vinyl		Carrying case, steel, for Cat. No. 514500-3	514500-3C
Instruction manual		Piezo verifier	510005
DETEX Phasing Testers		Pneumatic glove tester	512117
Carrying case, steel, for all models except			
Cat. No. 514500-3			
Carrying case, vinyl, for Cat. No. 514500-3			
Instruction manual			